

12340 World Trade Drive
San Diego, CA 92128
(858) 487-1600
FAX 487-6629

14. ADDED AS SECONDARY OPERATION.

3. ALL DIODES ARE TYPE 1N4003, EXCEPT AS NOTED.

2. ALL CAPACITORS IN MICORFARADS, EXCEPT AS NOTED.

1. ALL RESISTORS IN OHMS

NOTES: UNLESS OTHERWISE SPECIFIED.

CHANGES FOR DCM1000 ASSEMBLY: 80-01000

1. Add Q110, Q210 (Type: MJL 21194).

2. Add Q114, Q214 (Type: MJL 21193).

3. Add R169-R171, R269-R271 (0.22Ω).

4. Change C501, C502 to 10Kmf @ 80V.

CHANGES FROM REV B TOC

1. R98 FROM +15 TO -15 CORRECTION

2. ADDED C10 .1U

3. CORRECTED PLACEMENT OF HEADERS ON FRONT POT PCB FOR BRACKET.

CHANGES FROM REV B TOC

1. Q106, Q206 changed to TIP31

2. addedALTPart 5550 and 5400 to Q102, Q103, Q202, Q203

DRAWN BY:GEORGE DREYER

DATE:29 JUNE 2000

APPROVED:

DATE:

PCB NO:30-01500

REV:D

ASSY. NO:80-00600 80-01400 80-01000

REV:D B K

REVISED BY:GEORGE DREYER

DATE:23APRIL 2001

#1319 #1318

#1688