


REV D to E Changes:  
 #1 R60 = 0.47, R 22 = 10 ohms  
 #2 Add 1uf 50V capacitor  
 #3 (not shown, fix hum problem)  
 Re-locate JM8 and JM14 on traces

REV F Changes:  
 1 C48 FROM .0068 TO .022 50V  
 2 SEPARATED IC4 AND IC5 ON PCB  
 3 MOVED FRONT PCB EDGE,  
 JACKS  
 AND POTS



VAC	FUSE
120VAC	T1A
240VAC	T630mA

VAC	TR1
120VAC	5607-1612
240VAC	5607-1613

**SIMMONS DA-50**  
 REV F - FEB 28, 2008  
 KUSTOM AMPLIFICATION

rev F

updated linkage as far as possible

c48 from .0068 to .022

(5) pots moved up 0.5mm

(2) jacks moved down 1.25mm

added 0.5mm to pcb top

separated IC4 and IC5 more

