


# SP-404A

# SERVICE NOTES

*Issued by RJA*



SP-404A is different from SP-404SX in the following table.

Refer to the SP-404SX service notes for other contents.

| SP-404SX   |                |             | SP-404A    |                |               |
|------------|----------------|-------------|------------|----------------|---------------|
| Part Code  | Part Name      | Description | Part Code  | Part Name      | Description   |
| 5100006876 | TOP PANEL      |             | 5100058477 | TOP PANEL      |               |
| 5100006877 | REAR PANEL     |             | 5100058480 | REAR PANEL     |               |
| 5100006879 | RUBBER SW PAD  |             | 5100058481 | RUBBER SW PAD  |               |
| 5100008948 | OWNER'S MANUAL | ENGLISH     | 5100058532 | OWNER'S MANUAL | MULTILANGUAGE |

**Copyright © 2017 Roland Corporation**

All rights reserved. No part of this publication may be reproduced in any form without the written permission of Roland Corporation.