From: **Richard Pruchnicki** richardprune1@icloud.com
Subject: [Scan] 2016-10-24 17:20 page #3
Date: October 24, 2016 at 5:24 PM
To: ascottmay@gmail.com

--
Sent with Genius Scan for iOS.
http://dl.tglapp.com/genius-scan

7. DISCHARGE ALL POWER SUPPLY POINTS BEFORE SERVICING
8. ALL MEASUREMENTS TAKEN AT NOMINAL MAINS VOLTAGE
9. ALL MEASUREMENTS +\- 20%
10. TEST SIGNAL 1kHz, 25 mVAC AT PREAMP INPUT
11. ADJUST PREAMP FOR 2 VOLTS AC AT TP31/21
12. SET PRESENCE CONTROL AT 1
13. TP41 BIAS ADJUST: -37VDC EL-34, -47 6L6GC, -52 6550A
14. NEVER USE CHINESE OUTPUT TUBES,MECHANICALLY UNSTABLE

LXV Development

JAKE/RAKE SERIES AMPS
55/100W MODELS   F:\ACAD\SCHEM\JAKE

Sent from my iPhone