

This model does not have the push pull switch on the Master Volume Control. See drawing 010182, Revision F for this change.