Vox V125 LEAD HEAD / CLIMAX COMBO

All 4 EL34 :
100K + 10K via pin 6
(see side diag.)



Do these (plate) voltages need to be swapped too ???

None of this part matches what is actually in my amp.

V1,2 — ECC83 / 12AX7
V3 — ECC82 / 12AU7
V4 — ECC81 / 12AT7
V5,6,7,8 — EL34 / 6CA7

Found to be 47n
Replaced with 100n