



TP1 & TP2 - tune bias for 38mV

S.T.A.C.		
Randall RR 1-100 Refit		
P. Mitcheltree	Rev 1.0	Page 1 of 1
	11/16/2015	