

```

.tran 0 9.99m 0 10u
.step param in 3 5 .5
.meas tran Vrms rms(V(out))
.meas tran Power_Out param Vrms**2/8

```

```

.four 1k V(out)

```

