



⚠ = Safety Critical Component only replace with same type and rating

V1-3 ECC83 V4-7 EL84

| ISSUE | DESCRIPTION  | APPD. | DATE     |
|-------|--|-------|----------|
| 6     | 115V Mains fuse changed from 1.5A to 1.6A          | RJF   | 17/5/5   |
| 5     | Updated for 2005 Approvals                         | RJF   | 22/3/5   |
| 4     | Added CX1,CX2,RX1,RX2. Changed C50 from 1u to 47uF | RST   | 21/04/04 |



TITLE VC30-212  
VC30-210 , VC30-112  
PCB 9072\_7  
PART No

| DRAWN       | TRACED | CHECKED | APPROVED | DATE     |
|-------------|--------|---------|----------|----------|
| D.E.H.      |        |         |          | 20/06/95 |
| DRAWING No. |        |         | 2401     |          |