





Rhy Bright
100K Lin

Lead Bright
100K Lin

210V

218V

194V

147V

214V

231V

255V

Output Trans

489V

484V

Choke

5V Regulator

HT Fuse

Mains Fuse

VCC Supply GND. Link to G6 main GND, or leave floating.

Preamp grounded to Chassis via Standoff

Tap from PI Supply for Metro style FX Loop

Screen supply GND is tied to preamp GND

B+ link. Break here for standby switch or link if using DPDT standby switch

Mains GND to chassis GND

Standby

On / Off

Rhythm Gain
1M Log

Rhythm Master
1M Log

Lead Gain
1M Log

Lead Master
1M Log

Trebble
250K Lin

Middle
2K Lin

Bass
1M Log

Presence
25K Lin

710 CT

6.3VAC

5VAC

Power Transformer

240 VAC

