

Bias adjustment for the V100H (V2)

Simply adjust these two VR's.

No.1 - To adjust the CW13 : Measure the voltage between pin 8th of V7 and ground (the voltage of R79), adjust CW13 until the voltage is 0.3V.

No.2 - To adjust the CW14 : Measure the voltage between pin 8th of V5 and ground (the voltage of R77), adjust CW14 until the voltage is 0.3V.