




Repairs for John Auchman's Marshall DSL401



Input Jack Solder cracks



DI Jack Solder cracks



Heater Rectifier Solder cracks