





REVISIONS			
REV.	DESCRIPTION	DATE	APPROVED
A	EC 2630	21-MAR-01	dBL
B	EC 2767	09-APR-02	dBL
C	EC 2871	06-JAN-03	dBL
D	PR 1108	24-MAR-10	MTG

CAUTION: TO REDUCE THE RISK OF FIRE,
REPLACE FUSE WITH SAME TYPE AND RATING.
ATTENTION: UTILISER UN FUSIBLE
DE REMPLACEMENT DE MÊME TYPE ET CALIBRE.

FILE/DWG: SERVICE DIAGRAM
DATABASE: Z486P.PCB DATE: 14-JAN-10

△ C10 STUFFED AS JUMPER FOR PCB ASSEMBLY 0079641000.
△ C9 NOT STUFFED FOR PCB ASSEMBLY 0079641000.
1. SEE SHEET 1 FOR PRIMARY WIRING, TEST CONDITIONS,
AND TEST POINT VALUES.
NOTES: (UNLESS OTHERWISE NOTED)

THIS DOCUMENT CONTAINS INFORMATION OF A PROPRIETARY NATURE TO FENDER MUSICAL INSTRUMENTS AND IS SUBMITTED TO YOU IN CONFIDENCE AND SHALL NOT BE DISCLOSED OR TRANSMITTED TO OTHERS WITHOUT AUTHORIZATION FROM FENDER MUSICAL INSTRUMENTS.

CHECKED BY: *MTG*
DATE: 4/14/10
APPROVED BY: *MTG*
DATE: 4/16/10
DRAWN: D. LEWIS ENGR: D. LEWIS
DATABASE FILE: Z486P.PCB

Fender MUSICAL INSTRUMENTS
Corona, CA U.S.A.

TITLE: SERVICE DIAGRAM, COMBINED (PCB assy)
BLUES JUNIOR

SIZE	DRAWING NUMBER	REV.
C	0057275000	D
RELEASE DATE: 21-MAR-01		SHEET 2 OF 2