


05/26/09 for Energy Star Program add the following:
 R9=3K48, R10=10K, Q3=MMBT5551.
 Also re-connect S1 for stdby mode and change Q1 for 400V part.

- HW2 LNU14-40
- HW3 4-40 .375
- HW4 LED_SP .720
- HW5 LED_SP .720
- HW6 LED_SP .720

- HW11 SO.937
- HW7 LED_SP .720
- HW8 LED_SP .720
- HW9 LED_SP .720

- FID1 FIDUCIAL
- FID2 FIDUCIAL
- FID3 FIDUCIAL



11/11/08 Changed LED spacers 30900478
 1/13/09 Added swage spacers 30901853
 3/05/09 Deleted swage spacers HW10, 30901853