


- NOTES:
1. 'N/C' = NO CONNECTION
  2. 'WHT' = WHITE
  3. F1 FUSES ARE 3AG, SLO-BLO
  4. F2 FUSES ARE 3AG, FAST BLO, PIGTAIL.
  5. ALL PRIMARY WIRE UL TYPE 1015 OR 1007, 18 GA.
  6. P/N FOR STUDIO 220 TRANSFORMER = 560001A. SM-400/REDHEAD = P/N 560003A. BABY/ELECTRIC BLUE = 560005. GRAND PRIX PREAMP = 560006



SWR ENGINEERING, INC.  
12823 Foothill Blvd., Unit F  
SYLMAR, CA 91342

SCHEMATIC  
PRIMARY WIRING  
DOMESTIC + EXPORT  
ALL MODELS  
FEB. 22, 1990 DHN. S.H.R.  
NO. 1001 REV. C

