



ASSY PIN 07-103-02

NOTE: R11 & C7 DESIGNATORS ARE NOT USED.

NOTE: BIAS SETTING AS FOLLOWS:
 SET AP1 BIAS ADJUST CONTROL
 FOR 5mV ACROSS R61 WITH
 NO SIGNAL APPLIED, NO LOAD.

1	7/28/89	SWAPPED J21 PINS 1 & 2, CONNECTED J21 TO HEADPHONES TO DETACH FROM MAIN GND	N00062	REM
0	7/01/89	CONTROL ISSUE	R690512-01	REM
0	7/01/89	CONTROL ISSUE	ECR00047	REM