

B-15R CSB0004

Created June 1998 Transferred October 2007

SLM Electronics

A Division of St. Louis Music, Inc. 11880 Borman Dr St. Louis, MO 63146 Phone 314 569 0141

Service Department Phone 800 738 7563 Fax 314 567 7278

June, 1998		Customer Service Bulletin# CSB0004
Units Affected:		
	B-15	Serial Numbers: from AJYDJ60001 through AJYDJ60017
		from AJYDJ70013 through AJYDJ70034
		from AJYDJ80001 through AJYDJ80008
	B-15J	Serial Numbers: from AJZJJ70001 through AJZJJ70005
	B-15W	Serial Numbers: from AKAWJ70001 through AKAWJ70055
Concorn		

Concern:

The color labels at terminals **J40** (GREEN), and **J41** (ORANGE) are misidentified on the printed circuit board. Terminal J39 (BLACK) is correct and is of no concern. These are connect points for 3 wires from the audio output transformer secondary. These units <u>are</u> however wired correctly and do function properly. This could cause some confusion in servicing these units.

Corrective Action:

The proper wiring is as follows: (see drawing below)

GREEN wire to J 41; ORANGE wire to J 40; necessary.)

(BLACK wire to J 39 no correction

necessary.)

