



NOTES:

- REPLACE Q2 (2SC3381) WITH TWO 2SC2240BL (Q2 AND Q2A).
- MOVED C38 AWAY FROM EC JACK TO COMPLY W/ CSA REQUIREMENT.
- CHANGE R18 FROM 0.5K TO 4.5K.
- CHANGE C13 FROM 3.3UF 50V TO 4UF 50V.

BIAS ADJUSTMENT PROCEDURE:
 WITH POWER OFF, ADJUST POT R28 FULL COUNTER-CLOCKWISE.
 TURN POWER ON AND WAIT 5 SECONDS FOR TURN ON DELAY.
 TURN R28 CLOCKWISE UNTIL VOLTAGE ACROSS J5 READS 10 mVDC.

gallien technology

2234 INDUSTRIAL DRIVE
 SUCCUNTON CA 95068
 TEL: 925-224-8200
 FAX: 925-234-8200

REVISED RECORD		APPROVED: DATE:	
LTR	ECO INC.		
TITLES:		DATE:	
1001RB-II POWER AMP		7/10/01	
DESIGNED: R.A.G.		DRAWING NO: 406-0260-A7	
DRAWN: Noji		PART NO: 206-0260-A7	
ELEC:		COMPANY: GALLIEN KUEGER	
MECH:		D/A:	
RELEASED:		RELEASED:	

NOT VALID UNLESS STAMP IS RED