

Some resistor values are marked something else value in parentheses are marked values. Different measurements may be cause of parallel resistances

PIGNOSE AMPLIFIER 9V

Model No 7-100(R)
 Serial No 95/13973
 US Patents 3860755,
 D231537 and D240315
 drawn Hemmo P.

Q1,Q2 C9014
 Q3,Q4 TIP410
 Transformer values
 unknown
 D1 has blue body with
 black stripe on it(normal
 silicon diode?)

